



Best Master Furniture™

The Imported Furniture Specialist

KING BED ASSEMBLY INSTRUCTIONS item 1520

BOX LIST

E SideRail 2PCS
F Center Support bar 1PC

H Footboard 1PCS
I Small Slat 36PCS
J Feet 2PCS
K Metal Leg Support 4PCS
L LONG SLAT 2PCS



E



E



F



H



I




J



K



L



HARDWARE PACKED LIST IN BOX


(a) Allen Key ø5/16"	1PCS	(b) Bolt ø5/16"×1.5"	16PCS	(c) SCREW 1.5"	4PCS	(d) Flat Washer ø5/16"	30PCS
(e) Spring Washer ø5/16"	30PCS	(f) Bolt ø1/4"×1"	2PCS	(g) NUT ø5/16"	8PCS	(h) Rails plastic slat	26PCS
(i) Center plastic slat	26PCS	Wrench	Not provided	(j) Allen Key 5mm	1PCS	(k) Bolt ø5/16"×2"	8PCS

KING BED ASSEMBLY INSTRUCTIONS

item 1520


STEP 1

Fasten **J** to bottom of footboard (**H**) with screw (**c**).



STEP 2

Bolts to use for side rails, should already come pre-inserted on the HB. Place bolt (**b**), washers (**e**, **d**) and fasten to Headboard with preinstalled hardware, Repeat step 2 for Footboard. Do not tighten until step 3.




KING BED

ASSEMBLY INSTRUCTIONS

item 1520


STEP 3

Attach siderail (E) to headboard (G) and footboard (H) using bolt (b) and allen key (a) as shown in diagram. Do not tighten bolts completely until assembly is completed.



STEP 4

Attach center support (F) to headboard (G) by using bolt (b) through washers(e , d) as shown in diagram.




KING BED

ASSEMBLY INSTRUCTIONS

item 1520


STEP 5

Attach leg support (K) to center support bar (F) by using bolt (k), washers(e , d), nut (g), and tighten the nut(g) by wrench.



STEP 6

Insert center plastic slot (i) into holes on center support bar (F). Press firmly into place as shown in diagram. Attach rail plastic slat (h) using same procedure.






Best Master Furniture™
The Imported Furniture Specialist

KING BED ASSEMBLY INSTRUCTIONS item 1520

STEP 7

Insert small slat (I) into plastic slats (h , i) as shown in diagram. Attach long slat (L) to Siderail (E) with bolt f as shown.



STEP 8

Assembly is complete.

