




spare parts 1



A		x1	E		Center Support bar	x1
B		x1	F		Slat	x26
C		x2	G		Metal Leg Support	x2
D		x1				
	Footboard					
	Side Rail					
	Headboard					

a	 5/16*2" x4	f	 x12
b	 1/4*1" x18	g	 M5 x1
c	 5/16 x8	h	 M4 x1
d	 1/4 x18	i	 x1
e	 5/16 x4	j	 5/16*0.75" x4
k	 Center plastic slat x13	l	 Rails plastic sla x26

step 1

ASSEMBLY INSTRUCTIONS

The assembled bedstead should be complete done before this step




step 2


ASSEMBLY INSTRUCTIONS



Best Master Furniture™
The Imported Furniture Specialist



step 3



step 4

ASSEMBLY INSTRUCTIONS

